



EXPOSED TO VIEW CONNECTION NOTES

- 1. BOLTS SHALL NOT BE "TWIST OFF"**
- 2. BOLTS SPACING, OFFSETS, COPES AND OTHER EXPOSED CONNECTION DIMENSIONS TO BE THE SAME OR SIMILAR DIMENSION TO ACHIEVE OVERALL CONSISTENCY**
- 3. INSTALL AND ALIGN BOLT HEADS AS INDICATED ON DETAILS**
- 4. FABRICATE STEEL PER SHEAR PLATE LOCATIONS / ORIENTATION INDICATED ON DETAIL.**

J446-101-W-	S5.4.3	
-------------	--------	--